


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established.

T 2 N R 39 E X-14



DESCRIPTION OF CORNER EVIDENCE FOUND:

None. Found an unrecorded 1/2" rebar 42 feet South and 4 feet West of true corner position.

SEE SURVEY NUMBER 025-2014

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED

TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At position determined by survey, I set a 5/8" x 30" iron pin, 27 inches in the ground, with 2 1/2" aluminum cap marked as shown below, from which:

A 5/8" iron pin bears South a distance of 66.00 feet, with a yellow plastic cap marked BGB SURVEY MARKER.

A 15 inch Ponderosa Pine bears North 63° East, a distance of 35.45 feet, marked CW 1/16 S34 BT.

Set a steel fencepost approximately 1 feet North of the corner monument. Corner falls North approximately 42 feet and East 5 feet of a fence corner.

I hereby certify that the corner was perpetuated on August 26, 2014.

Witness: Thomas J. Kopp


UNION COUNTY SURVEYOR

Date Received 9/9/14

Date Filed 9/9/14

Filed By [Signature]

File Number 048-2014R



REGISTERED PROFESSIONAL LAND SURVEYOR

[Signature]

OREGON
June 2, 2010

JEFFREY S. HSU
83571

Renewal Date: June 30, 2015

I used a steel tape and magnetic compass in the establishment of the accessories. I used 16° East declination. The distances are to a 60d spike driven into the right side of the root crown of the bearing tree. A brass washer marked OPLS 83571 is attached to the BT blaze of the bearing tree.