


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner not previously established. This corner established by survey as defined in the 2009 Manual of Surveying Instructions.

Township 2 North, Range 40 East

E-2




Subsequent survey:

N/A

Description of evidence found:

N/A



Description of monument and accessories established to perpetuate the location of this corner.

At position determined by survey, I set a 2 ins. diam. aluminum cap, on a 5/8 ins. diam. x 30 ins long iron rod, marked as shown.
From which:

A Douglas fir, 14 ins. diam., bears S. 26° W., 18.8 ft. dist., marked "XBT".

A 5/8" x 30" long iron rod with yellow plastic cap marked "BROCKAMP LAND SURVEYING PLS 78556"
bears N. 42° W., 9.1 ft. dist.

Corner position falls in timber on gentle W. slope, 40 ft., E. of dirt road. Grande Ronde River courses N., 140 ft., E., and a N-S fence bears E., 100 ft.

Bearings are made with a hand compass, magnetic declination = 15°E.

I hereby certify that the above corner point was perpetuated as herein described on 6/13/2018.

Witnessed by:
Matt Brockamp, LS
Haley Brockamp

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
MAY 20, 2015
MATTHEW R. BROCKAMP
78556

Registration expires 12/31/2019

UNION COUNTY SURVEYOR	
Date Received	<u>7/19/18</u>
Date Filed	<u>9/13/18</u>
Filed By	<u>[Signature]</u>
File Number	<u>045-2018R</u>

