
UNION COUNTY CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner was originally set by Rufus S. Moore under GLO contract no. 382, dated March 23, 1881. Surveyor General record states:

Set basalt stone 16x9x7 for section corner. From which A pine 7 ins. dia bears S 12°E, 102 lks.

In 1904 road # 580 was surveyed on the East line of Section 10.



No record of subsequent monumentation found in Union County survey records.

Description of corner evidence found:

I found no evidence of the original corner.
I found the county road, a 24' gravel road, (60' between the fences), now called County road number 50, (Thompson Road).

There is a fence running East and the remains of a fence West.

See Map of Survey Number 015-1992.

Description of monument and accessories I established to perpetuate the

In the center of the existing county road and on the fence line, I set a 5/8" X 30" rebar with aluminum cap marked as shown, with the cap 5" below the road surface, marked as shown, from which;


A 5/8" x 30" rebar bears N67°E, 34.32 feet with 2" aluminum cap marked "NE RP".
A 5/8" x 30" rebar bears S44°E, 38.98 feet with 2" aluminum cap marked "SE RP".
A 12" ponderosa pine bears S36°W, 72.54 feet marked T2N P40E G10 DT

A 14" ponderosa pine bears S83°W, 61.34 feet marked X BT

Steel fence post 18 ft. east.

I hereby certify that the above corner point was perpetuated as hereon described on May 15, 1992.

Pete Crabtree Whitness:



REGISTERED PROFESSIONAL ND SURVEYOR

OREGON JULY 10, 1964 **DUANE I. GRIFFITH** 644

I used a steel tape and magnetic compass in the establishment of new accessories. I used 20° East magnetic declination. The distances are to a 50d spike driven in the right side of the root crown. I attached a brass washer marked OPLS 644 to the BT blaze.

UNION COUNTY SURVEYOR Date Received File No. 029-1992R

E - 17

5517