
UNION COUNTY CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner was never set.



No record of subsequent monumentation found in Union County survey records.

Description of corner evidence found:

See Map of Survey Number 015-1992.

Description of monument and accessories I established to perpetuate the original location of this corner:

At position determined by survey, I set a $5/8" \times 30"$ rebar with aluminum cap marked as shown, 26 inches in the ground, from which:

Set a steel fence post 1 foot south.

The corner is near the P.I. of county road # 50.

An east-west fence line, (on the right of way), is 30 feet south.

I hereby certify that the above corner point was perpetuated as hereon described on May 15, 1992

Whitness: Pete Crabtree

R40E T2N SE 1/16 S 10 1992 OPLS 644

REGISTERED PROFESSIONAL AND SURVEYOR

OREGON JULY 10, 1964 DUANE I. GRIFFITH

> UNION COUNTY SURVEYOR

Date Received 6

Date Filed 6/20/

File No. 037- 1992 K

H-16

5816