

UNION COUNTY SURVEYOR

CERTIFIED RECORD OF LAND CORNER MONUMENTATION


HISTORY OF ORIGINAL CORNER ESTABLISHMENT:
Corner not previously established.

No record of monumentation found in UNION COUNTY survey records.

DESCRIPTION OF CORNER EVIDENCE FOUND:
Corner not previously established.

See Survey Number 016-1998.

T 2 N R 40 E K-02



DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position determined by said survey, I set a 5/8" x 30" Rebar with 1 1/2" aluminum cap marked as shown below, 28" in the ground, from which:


NEW BEARING OBJECTS:

A 5" diameter Douglas Fir bears N 59° E, a distance of 40.51 feet marked X BT.

A 10 1/2" Douglas Fir bears S 80° W, a distance of 31.50 feet, marked NW 1/16 S 18 BT.

I hereby certify that the corner was monumented on May 8, 1998.
Witness: Greg Blackman Jr., John Anderson

REGISTERED
PROFESSIONAL
LAND SURVEYOR



OREGON
JULY 13, 1973
GREGORY T. BLACKMAN
991

Renewal Date: December, 31 1999

BAGETT - GRIFFITH & BLACKMAN

NW1/16

S 18
1998

OPLS 991

**UNION COUNTY
SURVEYOR**

Date Received 5/15/98

Date Filed 8/29/98

Filed By R. Anderson Deputy

File Number 041-1998R

I used a steel tape and magnetic compass in the establishment of new accessories. The magnetic declination used was 17° East. The distance to the bearing trees is to a 50d spike driven on the right side of the tree at the root crown. I attached a brass washer marked OPLS 991 to the BT blaze.