
CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established

T2N R40 EK-14



DESCRIPTION OF CORNER EVIDENCE FOUND:

None

SEE SURVEY NUMBER 029-2022

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO MONUMENT THE ORIGINAL LOCATION OF THIS CORNER:

At position by survey, I set a 5/8" x 30" iron pin, 26" in the ground, with 2 1/2" aluminum cap marked as shown and in a 2 ft. diam. collar of stone, from which:

NEW BEARING OBJECTS:

A 5/8" x 30" iron pin bears South 88°28' East a dist. of 30.00 ft., marked "E RP BGB SURVEY MARKER" A 5/8" x 30" iron pin bears South 0°09' West a dist. of 30.00 ft., marked "S RP BGB SURVEY MARKER"

Set steel fence post approx. 1 ft. West

Fence corner to South/East bearing fencelines bears approx. 10' Southeast

I hereby certify that the corner was monumented on September 7, 2022.

Witness: Dan S. Drum, Kyle A. Tucker

T2N R40E 8/4 CARANTER STEEL ST

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
June 2, 2010

JEFFREY S. HSU
83571

Renewal Date: June 30, 2023

I used a Leica GS18 RTK in the establishment of the new accessories. Basis of Bearing is as per Survey Number 029-2022. Distances and bearings are to the centers of the aluminum caps.

UNION COUNTY
SURVEYOR

Date Received 9/16/27

Date Filed By 6/16/12

Filed By 6/16/1