


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner originally established by James D. Hanley on Union County Survey 5-85, dated May 1984.
Survey states:
Set 5/8" rebar with yellow plastic cap marked Hanley ENGR PLS 1206. Staked for fencing to the South.

T 2 N R 40 E K-15



DESCRIPTION OF CORNER EVIDENCE FOUND:

Found a 5/8" x 30" iron pin bears North 86° West, a dist. of 118.95 ft., with yellow plastic cap marked Hanley ENGR PLS 1206.

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO MONUMENT THE ORIGINAL LOCATION OF THIS CORNER:

At position by survey I set a 5/8" x 30" iron pin, 31" in the ground, with 2 1/2" aluminum cap marked as shown below, from which:

NEW BEARING OBJECTS:

A 7" Ponderosa Pine bears North 5° East a dist. of 45.75 ft., marked CN 1/16 S15 BT.
An 11" Douglas Fir bears South 23° West a dist. of 6.50 ft., marked CN 1/16 S15 BT.


I hereby certify that the corner was monumented on September 03, 2019.
Witness: Kyle A. Tucker

REGISTERED
PROFESSIONAL
LAND SURVEYOR



OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2019



UNION COUNTY
SURVEYOR

Date Received 12/31/19

Date Filed 12/31/19

Filed By NLG

File Number 076-201912

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 13° East declination, the distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.