

CERTIFIED RECORD OF LAND CORNER MONUMENTAL

History of original corner establishment:

Section corner common to Sections 13 & 24, T2N, R39E and Sections 18 & 19, T2N, R40E, W.M., Union County, Oregon.

Original corner established in 1864 by T. Davenport under contract No. 102 approved 1/12/1864. He set a post for the section corner common to sections 13, 24, 18 & 19 from which:

- Tamarac 24" in diameter bears N22°E, 79 Lks. distance.
- Tamarac 24" in diameter bears N77°W, 40 Lks. distance.
- A Fir 22" in diameter bears S16°W, 41 Lks. distance.
- A Fir 40" in diameter bears S49°E, 45 Lks. distance.

REGISTERED PROFESSIONAL LAND SURVEYOR

B. A. Sutton
OREGON
JULY 13, 1979
B. A. SUTTON
1848

RENEWAL 6/30/98


Description of corner evidence found:

No original corner evidence found. Original corner reference found as follows:

A 40" fir stump bears S49°E, 45 Lks. "BT" visible in blaze.

Description of monument and accessories I established to perpetuate the original location of this corner:

I set a 5/8"x30" iron rod with a 1-1/2 inch aluminum cap marked: at N49°W, 45 Lks from the above described Original BT stump.



I established the following references:

- A 10" Douglas Fir bears N45°15'E, 62.3' blazed & scribed; (T2NR40ES18BT)
- A 10" Douglas Fir bears S27°45'E, 23.1' blazed & scribed; (T2NR40ES19BT)
- An 11" Douglas Fir bears S44°45'W, 17.4' blazed & scribed; (T2NR39ES24BT)
- A 9" Douglas Fir bears N39°30'W, 28.4' blazed & scribed; (T2NR39ES25BT)

Office of the County Surveyor County of Union

State of Oregon, I hereby certify that the within instrument was filed in this office

for record on the _____ day of _____, 19_____

_____ by _____
(COUNTY OFFICIAL)

_____ by _____
(DEPUTY)

UNION COUNTY SURVEYOR

Date Received 9/16/96

Date Filed 10/5/96

By [Signature]

File No. 104-1996R