

Dependent Resurvey of a Portion of the Subdivisional Lines,
T. 2 S., R. 34 E., Willamette Meridian, Oregon

CHAINS

From the cor. of secs. 28, 29, 32, and 33, perpetuated by person(s) unknown, monumented with an iron pipe, 1 in. diam., firmly set, protruding 6 ins. above ground, in a collar of stone, from which the remains of an original bearing tree:

A root hole, bears S. 30° E., 45 lks. dist., with a down pine, 15 ins. diam., lying alongside, with scribe marks S33 BT on partially healed blaze.

At the corner point

Set a stainless steel post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, in a collar of stone, with brass cap mkd.

T 2 S R 34 E
S 29 | S 28
S 32 | S 33
1987

T2S34
V09

from which new bearing trees

A fir, 15 ins. diam., bears N. 3½° E., 44½ lks. dist., mkd. T2S R34E S28 BT.

A fir, 16 ins. diam., bears S. 22½° E., 60½ lks. dist., mkd. T2S R34E S33 BT.

A larch, 21 ins. diam., bears S. 73½° W., 184½ lks. dist., mkd. T2S R34E S32 BT.

A fir, 17 ins. diam., bears N. 76¾° W., 68 lks. dist., mkd. T2S R34E S29 BT.

Deposit a white "DEEP-1" magnetic marker at the base and the iron pipe alongside the stainless steel post.

The corner is located on SE. slope, in timber and light undergrowth.

S. 0° 12' 30" W., bet. secs. 32 and 33.

Over broken E. slope.

- 6.90 Spur, slopes S. 60° E.; desc. over broken SE. slope, through light timber.
- 26.25 Base of steep SE. slope; thence over level ground.
- 26.75 McCoy Creek, dry, 20 lks. wide, drains N. 55° E.

UNION COUNTY
SURVEYOR

Date Received 3/8/13
Date Filed 3/8/13
By [Signature] DEPUTY
File No. 222-2013R