## Dependent Resurvey of a Portion of the Subdivisional Lines, T. 2 S., R. 34 E., Willamette Meridian, Oregon

From this same point, the original closing cor. of secs. 34 and 35, for the north side of the Reservation boundary, perpetuated by Barry B. Barbour, Registered Land Surveyor No. 1051, in 1980, ears S. 0° 17′ 00″ W., 0.090 chs. dist., monumented with an iron post, 2 ins. diam., firmly set, protruding 13 ins. above ground, with brass cap mkd. T2S R34E CC S34 S35 UIR 1917, from which the remains of the bearing trees mkd. by Wilkes:

## **UNION COUNTY** SURVEYOR

Date Received 3/8/13

3/8/13 Date Filed

File No.

- A root hole, bears N. 73% W., 38 lks. dist., with lodge pole pine, ll ins. diam., lying alongside with scribe warks T2S R34E CC S35 UIR BT on partially healed blaze. Record, N. 15° E., 39 Iks.)
- A root hole, bears N. 44 $^{\circ}$  W., 33 lks. dist., with a pine, 14 ins. diam., lying alongside, with illegible scribe marks on partially healed Maze.

and bearing trees mkd. by Barbour

- A fir, 14 ins. diam., bears N. 27° E., 15 lks. dist., with scribe marks T2S R34E S35 BT on partially healed blaze.
- A larch, 16 ins. diam., bears N. 04° W., 130 1ks. dist., with scribe marks T2S R34E S34 BT on partially healed blaze.

Mark the brass cap AM and bury the iron post in place.

From the ½ sec. cor. of secs. 34 and 35.

N. 0° 05' $\sqrt{00}$ " W., bet. secs. 34 and 35.

Ascend broken SE. slope, through timber and light undergrowth.

t road, 15 lks. wide, bears N. 80° E. and S. 80° W. 5.50

Top of ascent; thence over level ground. 12.60

20.095 Point for the N 1/16 sec. cor. of secs. 34 and 35.

> Set a stainless steel post, 28 ins. long, 2½ ins. diam., 8 ins. in the ground, to solid rock, supported in a mound of stone, 3 ft. base, to top, with brass cap mkd.

> > N 1/16s 34 s 35 1987

T2534 WI7 Dependent Resurvey of a Portion of the Subdivisional Lines, T. 2 S., R. 34 E., Willamette Meridian, Oregon

CHAIRS

from which

- A ponderosa pine, 14 ins. diam., bears S.  $55^{\circ}$  E.,  $52\frac{1}{2}$  1ks. dist., mkd. N 1/16 S35 BT.
- A lodgepole pine, 7 ins. diam., bears S.  $29\frac{3}{4}^{\circ}$  W.,  $18\frac{1}{2}$  lks. dist., mkd. N 1/16 S34 BT.

Deposit a white "DEEP-1" magnetic marker at the base and set a steel fence post alongside the stainless steel post.

39.85

Gravelled road, 20 lks. wide, bears N. 60 W. and S. 60 F

40.190

The cor. of secs. 26, 27, 34, and 35, monumented with the point of the original wood post, firmly set flush with the ground, with the original wood post, 3  $\times$  3 ins., with scribe mark S, lying alongside and a mound of stone, 3 ft. base, 1 ft. high, N. of the corner, from which an original bearing tree:

A larch, 31 ins. diam., bears N. 60% F., 78% lks. dist., no marks on rotted and burned blaze. (Record, pine, N. 62° E., 76 lks.)

UNION COUNTY
SURVEYOR

At the corner point

Date Received 3/8/13

Set a stainless steel post, 28 ins. long,  $2\frac{1}{2}$  ins. diam., 24 ins. in the ground, with brase cap mkd.

Date Filed 3/8/13

2 S R 34 E 3 27 | S 26 S 34 | S 35

TILE NO. 233-2013R

from which new bearing trees

- A fir, 19 ins. diam., bears S. 26° E., 151 1ks. dist., mkd. T2S R34E S35 BT.
- A fir, 12 ins. diam., bears S.  $42\frac{1}{2}^{\circ}$  W.,  $106\frac{1}{2}$  1ks. dist., mkd. T2S R34E S34 BT.
- A fir, 11 ins. diam., bears N.  $39\frac{1}{2}^{\circ}$  W., 21 lks. dist., mkd. T2S R34E S27 BT.

Deposit a white "DEEP-1" magnetic marker at the base and the original wood post and a steel fence post alongside the stainless steel post.