

Retracement-Resurvey of the South Boundary  
Original Umatilla Indian Reservation

Chains

T25R34E  
UIR WC  
64M  
1917

UNION COUNTY SURVEYOR	
Date Received	3/11/13
Date Filed	3/11/13
By	<i>[Signature]</i> DEPUTY
File No.	276-2013R

from which

A pine, 24 ins. diam., bears N.49°30'W., 252 lks. dist., marked U I R 64 M B T.

A pine, 6 ins. diam., bears N.21°45'E., 133 lks. dist., marked U I R 64 M B T.

thence

S.89°49'E., resurveying the 64th Mile

over mountainous land, not very rough, through heavy timber and medium undergrowth.

Descend 210 ft. to

16.25 Road, bears N. and S., in gulch, course S.; ascend 175 ft. to

28.80 Top of ascent, descends NW.

Descend on NE. and E. slope, 125 ft. to

34.87 The closing cor. of secs. 34 and 35, which is an old post, much decayed, marked C C U R on N. face. In its place Set an iron post, 3 ft. long, 2 ins. diam., 24 ins. in the ground, for closing cor. of secs. 34 and 35, with brass cap marked

T25R34E  
C|C  
S34|S35  
1917

from which

A fir, 16 ins. diam., bears S.19°50'W., 25 lks. dist., blazes grown over and unopened.

Other tree dead and fallen.

A lodgepole pine, 8 ins. diam., bears N.15°E., 39 lks. dist., marked C C T 2 S R 34 E S 35 U I R B T. (new B.T.)

A lodgepole pine, 6 ins. diam., bears N.44°W., 33 lks. dist., marked C C T 2 S R 34 E S 34 U I R B T (new B.T.)

40.13 The 63 $\frac{1}{2}$  Mile Cor., the position of which is determined

445

Dependent Resurvey of a Portion of the Subdivisional Lines,  
T. 2 S., R. 34 E., Willamette Meridian, Oregon

CHAINS

T 2 S R 34 E  
1/4  
S 34 | S 35  
1987

UNION COUNTY  
SURVEYOR  
Date Received 3/8/13  
Date Filed 3/8/13  
By [Signature] DEPUTY  
File No. 247-2013R

from which new bearing trees

A ponderosa pine, 15 ins. diam., bears S. 14 1/4° E.,  
33 lks. dist., mkd. 1/4 S35 BT.

A ponderosa pine, 11 ins. diam., bears S. 50 1/2° W.,  
67 lks. dist., mkd. 1/4 S34 BT.

Deposit a white "DEEP-1" magnetic marker at the base and a steel  
fence post alongside the stainless steel post.

S. 0° 17' 00" W., bet. secs. 34 and 35.

Descend SE slope, through timber and light undergrowth.

9.830 Intersect the S. bdy. of the Umatilla Indian Reservation.

True point for the closing cor. of secs. 34 and 35 for the north  
side of the Reservation boundary.

Set a stainless steel post, 28 ins. long, 2 1/2 ins. diam., 24 ins.  
in the ground, with brass cap mkd.

T 2 S R 34 E  
C | C  
S 34 | S 35  
S 34  
1987

from which

A fir, 9 ins. diam., bears N. 71 1/4° E., 41 1/2 lks. dist.,  
mkd. T2S R34E S35 CC BT.

A fir, 14 ins. diam., bears N. 30 1/2° W., 37 1/2 lks. dist.,  
mkd. T2S R34E S34 CC BT.

Deposit a white "DEEP-1" magnetic marker at the base and set a  
steel fence post alongside the stainless steel post.

From this point, the 64 Mile Corner on the S. bdy. of the  
Umatilla Indian Reservation, bears N. 89° 40' 30" W., 34.790 chs.  
dist., hereinbefore described.

Dependent Resurvey of a Portion of the Subdivisional Lines,  
T. 2 S., R. 34 E., Willamette Meridian, Oregon

CHAINS

From this same point, the original closing cor. of secs. 34 and 35, for the north side of the Reservation boundary, perpetuated by Barry B. Barbour, Registered Land Surveyor No. 1051, in 1980, bears S.  $0^{\circ} 17' 00''$  W., 0.090 chs. dist., monumented with an iron post, 2 ins. diam., firmly set, protruding 13 ins. above ground, with brass cap mkd. T2S R34E CC S34 S35 UIR 1917, from which the remains of the bearing trees mkd. by Wilkes:

A root hole, bears N.  $73\frac{1}{2}^{\circ}$  W., 38 lks. dist., with a lodgepole pine, 11 ins. diam., lying alongside, with scribe marks T2S R34E CC S35 UIR BT on partially healed blaze. (Record, N.  $15^{\circ}$  E., 39 lks.)

A root hole, bears N.  $44^{\circ}$  W., 33 lks. dist., with a pine, 14 ins. diam., lying alongside, with illegible scribe marks on partially healed blaze.

and bearing trees mkd. by Barbour

A fir, 14 ins. diam., bears N.  $27^{\circ}$  E., 15 lks. dist., with scribe marks T2S R34E S35 BT on partially healed blaze.

A larch, 16 ins. diam., bears N.  $64^{\circ}$  W., 130 lks. dist., with scribe marks T2S R34E S34 BT on partially healed blaze.

Mark the brass cap AM and bury the iron post in place.

UNION COUNTY  
SURVEYOR

Date Received 3/8/13

Date Filed 3/8/13

By J/L DEWITT

File No. 247-2013R

From the  $\frac{1}{2}$  sec. cor. of secs. 34 and 35.

N.  $0^{\circ} 05' 00''$  W., bet. secs. 34 and 35.

Ascend broken SE. slope, through timber and light undergrowth.

5.50 Dirt road, 15 lks. wide, bears N.  $80^{\circ}$  E. and S.  $80^{\circ}$  W.

12.60 Top of ascent; thence over level ground.

20.095 Point for the N  $1/16$  sec. cor. of secs. 34 and 35.

Set a stainless steel post, 28 ins. long,  $2\frac{1}{2}$  ins. diam., 8 ins. in the ground, to solid rock, supported in a mound of stone, 3 ft. base, to top, with brass cap mkd.

N 1/16  
S 34 | S 35  
1987