## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

## HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner originally established by Rufus S. Moore under GLO Contract Number 451, dated June 12, 1882.

Surveyor General record states:

Set a post 3 ft. long, 3 ins. sq., 24 ins. in the ground for 1/4 sec cor. Marked 1/4 S on W face. From which:

A fir 5 ins. in dia. bears N82°E, 31 lks. dist., marked 1/4~S

A tamarack 9 ins. in dia. bears S60°W, 28 lks. dist., marked 1/4 S BT.

## T 2 S R 35 E G-17

## DESCRIPTION OF CORNER EVIDENCE FOUND:

NONE

SEE SURVEY NUMBER 016-2014

Description of monument and accessories  $\,\,$  I established to perpetuate the original location of this corner:

At a proportionate position, I set a  $2 \, \frac{1}{2}$ "x30" aluminum pipe with a  $2 \, \frac{1}{2}$ " aluminum cap 24" in the ground, marked as shown below, from which:

A 8" Spruce bears N 48° E, a distance of 8.20 feet, marked 1/4 S11 BT.

A 10" Spruce bears S 26° E, a distance of 21.14 feet, marked 1/4 S11 BT.

A 14" Spruce bears S 44° W, a distance of 5.73 feet, marked 1/4 S10 BT.

A 14" Spruce bears N 28° W, a distance of 8.90 feet, marked 1/4 S10 BT.

Set a steel fencepost approximately 1 foot North of corner monument.

I hereby certify that the corner was monumented on May 22, 2014.

Witness: Thomas J. Kopp

REGISTERED
PROFESSIONAL
LAND SURVEYOR
OREGON

JEFFREY S. HSU 83571

Renewal Date: June 30, 2015

T2S R35E

T2S R35E

T4

S10 S11

2014
OPLS 83571

UNION COUNTY SURVEYOR

T:1- 3 D.,

File Number 019-2014

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 16° East declination, the distances are to a 60d spike driven into the right side of the root crown of the new bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.