


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established.

T 2 S R 35 E J-14



DESCRIPTION OF CORNER EVIDENCE FOUND:

None.

SEE SURVEY NUMBER 015-2016

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED

TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At position determined by survey, I set a 5/8" x 30" iron pin, with 2" aluminum cap attached, marked as shown below, 26" in the ground, in a collar of stone 2 ft. diam., from which:

NEW BEARING OBJECTS:

A 12 inch Douglas Fir bears North 64° East, a distance of 11.30 feet, marked W1/16 S10 BT.
A 14 inch Douglas Fir bears South 23° West, a distance of 20.75 feet, marked W 1/16 S15 BT.


Set a steel fencepost approx. 0.5 ft. South of corner monument.

I hereby certify that this monument was set May 13, 2016.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2017



**UNION COUNTY
SURVEYOR**

Date Received 5/16/16

Date Filed 5/16/16

Filed By [Signature]

File Number 013-2016R

I use a steel tape and magnetic compass in the establishment of the accessories. Magnetic declination used was 15° East. Distances are to a 60d spike in the right hand side of the root crown of the bearing trees.