

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

Corner not previously established


DESCRIPTION OF CORNER EVIDENCE FOUND:

None.

See Survey Number 030-2008

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At position determined by survey, I set an 2 1/2" x 30" aluminum pipe with 2 1/2" aluminum cap 24" in the ground in mound of stone 1 1/2 ft. base to top of cap, from which:



NEW BEARING TREES:

A 10" diameter Western Larch bears North 80° East, a distance of 43.80 feet, marked C1/4 S14 BT.

An 8" diameter Western Larch bears South 4° East, a distance of 7.95 feet, marked C1/4 S14 BT.

A 10" diameter Douglas Fir bears South 87° West, a distance of 31.00 feet, marked C1/4 S14 BT.

A 12" diameter Douglas Fir bears North 41° West, a distance of 39.50 feet, marked C1/4 S14 BT.

I hereby certify that the corner was monumented on September 22, 2008.

Witness: Greg Blackman Jr., Jeff Hsu

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Rick G. Robinson

OREGON
July 17, 1986

RICK G. ROBINSON
2219

Renewal Date: December 31, 2008

BAGETT - GRIFFITH & BLACKMAN

T2S R35E

C1/4 S14

2008

OPLS 2219

**UNION COUNTY
SURVEYOR**

Date Received 10/6/08

Date Filed 10/6/08

Filed By *[Signature]*

File Number 012-2008R

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 18° East declination, the distances are to a 60d spike driven into the right side of the root crown of the bearing tree. I attached a brass washer marked OPLS 2219 to the BT blaze.