


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:
Not established during original survey.

Index File No. 0-20



Description of corner evidence found:
None.

Description of monument and accessories established to perpetuate the original location of this corner:

Corner location determined by survey and subdivision of Section 23.

At surveyed point set: A 2 1/2" x 30" galvanized pipe with brass cap attached 24" in the ground stamped:

T2S R35E
NE 1/16 S23
1981
OR PLS 1099

From which:

A 14" Ponderosa Pine bears S72° E 16.2 ft. scribed NE 1/16 S23 BT.

A 12" Douglas Fir bears S 74° W 14.3 ft. scribed NE 1/16 S23 BT.

Attached 54-3 and 54-4 signs and painted blazes and red ring around both BT's. Attached brass washers LS 1099 to foot blazes. Set metal fence post 5' north of corner with 54-2 and 54-4 signs. Set metal fence post 5' east of corner with 54-2 and 54-9 signs.

Corner falls on level ground 37 ft. north of dirt road.

Compass Declination: 18 1/2° East

I hereby certify the above described corner monument and/or accessories was established as described on November 6, 1981.

Witnesses: Loren Huntsman
Millard Wyatt

Office of Surveyor County of Union
 State of Oregon, I hereby certify that the within instrument was filed in this office
 for record on the 4 day of OCTOBER, 1982
Howard L. Perry by Gary L. Langlitz
 (COUNTY OFFICIAL) (DEPUTY)



UNION COUNTY
SURVEYOR

Date Received _____

Date Filed _____

By _____

File No. 209-84 R