


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. P-21

History of original corner establishment:

In 1882 under GLO contract #451 Rufus S. Moore set a basalt stone 14x12x10-11 inches in the ground for 1/4 Cor. between S23 and S24. Marked 1/4 on West fence. From which:

- A 23" Tamarack bears N43°E 341ks.
- A 32" Pine bears N68°W 34 1ks.




Description of corner evidence found:

Could find no evidence of original stone or BT's. This corner falls just below a road and may have been destroyed during the building of this road.

Description of monument and accessories | established to perpetuate the original location of this corner:

At single proportion measurement between the NE & SE corners of S23 T2S R35E set 2 1/2"x30" galvanized pipe with brass cap 24" in ground stamped:



Bearing trees:

- A 9" Douglas Fir bears S81°E 8.8 ft. scribed 1/4 S24 BT
- An 18" Douglas Fir bears S54°W 43.3 ft. scribed 1/4 S23 BT.

Attached 54-3 and 54-4 signs to both Bt's. Painted blazes and red ring around BT's. Attached brass washers 1099 to foot blazes. Set metal fence post 5' North of corner with 54-4 sign.

Corner falls on NW slope 25' West of dirt road.

Compass Declination 18 1/2° East.

I hereby certify the above described corner monument and/or accessories was established as described on November 9, 1981.

Witnesses: Loren Huntsman
Millard Wyatt



Office of..... Surveyor..... County of..... Union.....
 State of..... Oregon..... I hereby certify that the within instrument was filed in this office
 for record on the 4 day of OCTOBER..... 1982
 Howard L. Perry..... by *Gary L. Langlitz*.....
 (COUNTY OFFICIAL) DEPUTY

UNION COUNTY SURVEYOR

Date Received _____
 ☆ GPO—798-276

Date Filed _____

By _____

File No. 214-84 R