


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. P-23

History of original corner establishment:

Not established during original survey.



Description of corner evidence found:

None

Description of monument and accessories established to perpetuate the original location of this corner:

Corner location determined by survey and subdivision of Section 24.

At Surveyed Point:

Set 2 1/2" x 30" galvanized pipe with brass cap attached 24" in the ground stamped:

T2S R35E
 C1/4 | S24
 1981
 OR PLS 1099

From which:

A 6" Douglas Fir bears N 17° E 5.8 ft. scribed C 1/4 S24 BT
 A 10" Douglas Fir bears S23°W 20.5 ft. scribed C 1/4 S24 BT

Attached 54-3 and 54-4 signs to BT's. Painted blazes and red 6" ring around BT's. Attached brass washers LS 1099 to foot blazes. Set metal post 5' north of corner with 54-4 and 54-9 signs.

Corner falls on steep north-west slope in scattered trees 80 ft. north of top of hill.

Compass Declination: 18 1/2° East

I hereby certify the above described corner monument and/or accessories was established as described on November 17, 1981.

Witnesses: Loren Huntsman Millard Wyatt
 Jeff Anderson Greg Orton



Office of..... Surveyor..... County of..... Union.....
 State of..... Oregon..... I hereby certify that the within instrument was filed in this office
 for record on the... A... day of... OCTOBER....., 1982
 Howard L. Perry..... by Gary L. Langlitz.....
 (COUNTY OFFICIAL) (DEPUTY)

UNION COUNTY SURVEYOR

Date Received _____
 ☆ GPO—798-276
 Date Filed _____
 By _____
 File No. 215-84 R