CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. R-19

History of original corner establishment:

In 1882 under G.L.O. Contract No. 451 Rufus S. Moore set a post 3'long 3" sq. 24" in the ground for 1/4 Sec. Cor 23, 26. From which: A Fir 4" in dia. bears N. 43°E 14 lks. A Tamarack 20" in dia. bears S41°W 13 lks.

DIAGRA	AM	
T2S	R35E	
1	23	
4 –	26	

Description of corner evidence found:

Found: A down snag, a 20" Tamarack with visible scribing 1/4 S BT. This was the S.W. BT so we pulled over recorded distance and direction. Could find no other evidence.

Description of monument and accessories I established to perpetuate the original location of this corner:

At the $\underline{\text{True Corner Point}}$, we set a 2"x30" Galvanized Iron Pipe, 26" in the ground with brass cap stamped:

From Which:

T2S R35E S23 **S26** 1981

OR PLS 1099

The original SW BT, a 20" Tamarack snag bears S41°W 8.6 ft.

New BT's

A 9" White Fir bears N 45°E 9.6 ft. scribed 1/4 S23 BT A 9" White Fir bears S21°E 10.4 ft. scribed 1/4 S26 BT

Attached 54-3, 54-4 signs to BT's. Painted blazes and ring around tree washer set in foot blase "1099". Set fence post with 54-4.

Compass Declination: 18 1/2° East

I hereby certify the above described corner monument and/or accessories was established as described on Oct. 5, 1981.

Witnesses: Loren Huntsman Millard Wyatt Jeff Anderson

REGISTERED PROFESSIONAL AND SURVEYOR

LANGLITZ 1099

_	
Office of Surveyor County of Union	••••••
State of Oregon , I hereby certify that the within instrument was filed in this for record on the 4 day of OCIDBER 1982	UNION COUNTY SURVEYOR
Orm R6-7100-57 (9/71)	Date Received
	☆ GPO-798-276