


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

T.5 - 18.5

History of original corner establishment:  
Corner was established as part of this survey.



Description of corner evidence found:

None.

Description of monument and accessories established to perpetuate the original location of this corner:

At position established by survey:

Set a 2½" X 30" aluminum pipe with a 2½" aluminum cap, buried 16" in the ground, and surrounded with a mound of earth and stone.

Set 6' steel fence post 4' North of monument with signs 54-2 and 54-9 attached.

Set 6' steel fence post 4' East of monument with sign 54-9 attached.

New bearing trees established:

A 17" ponderosa pine bears N 30¼° E - 33.5 ft., scribed "NE-SW 1/64 S26BT".

A 12" ponderosa pine bears N 44° W - 16.1 ft., scribed "NE-SW 1/64 S26BT".

New bearing trees have a brass washer stamped "PLS 1106" nailed to face of blaze. Attached sign 54-3 & 54-9, painted face of blaze & a 6" red band around each tree.

Bearing trees were tied using a Sokkia Automatic Total Station.

I hereby certify that the above corner monument was properly monumented to U.S.F.S. standards by me on November 16, 1994.

Compass declination 18° East.

Witnessed by: Greg E. Flowers, LSIT  
Todd Rosenbalm

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*William R. Wells*

OREGON  
JULY 22, 1977  
WILLIAM R. WELLS  
1106

*renews 6/30/98*

Office of..... County of.....  
State of..... I hereby certify that the within instrument was filed in this office  
for record on the..... day of....., 19.....

..... by.....  
(COUNTY OFFICIAL)

UNION COUNTY  
(DEPUTY) SURVEYOR

Date Received 7-10-96  
Date Filed 7-10-96  
By R. ROBINSON, DEPUTY  
File No. 075-1996R

GPO-591-971, 1988