


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

T- 18.5

History of original corner establishment:  
Corner established as part of this survey.



**Description of corner evidence found:**

None.

**Description of monument and accessories I established to perpetuate the original location of this corner:**

At position established by survey:

Set a 2½" X 30" aluminum pipe with a 2½" aluminum cap, buried 10" in the ground, and surrounded with a mound of earth and stone.

Set a 6' steel fence post 4' South of monument with sign 54-2 attached.

Set a 6' steel fence post 4' East of monument with signs 54-2 and 54-9 attached.

New bearing trees established:

A 22" ponderosa pine bears N 54 3/4° E - 54.1 ft., scribed "C-E-W 1/64 S26BT".

A 26" ponderosa pine bears N 73¼° W - 105.1 ft., scribed "C-E-W 1/64 S26BT".

New bearing trees have a brass washer stamped "PLS 1106" nailed to face of blaze. Attached sign 54-3 & 54-9, painted face of blaze & a 6" red band around each tree.

Bearing trees were tied using a Sokkia Automatic Total Station.

I hereby certify that the above corner monument was properly monumented to U.S.F.S. standards by me on November 16, 1994.

Compass declination 18° East.

Witnessed by: Greg E. Flowers, LSIT  
Todd Rosenbalm

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*William R. Wells*

OREGON  
JULY 22, 1977  
WILLIAM R. WELLS  
1106

*renews 6/30/98*

Office of..... County of.....

State of....., I hereby certify that the within instrument was filed in this office

for record on the..... day of....., 19.....

..... by .....  
(COUNTY OFFICIAL)

**UNION COUNTY**  
SURVEYOR  
(DEPUTY)  
Date Received 7-10-96  
Date Filed 7-10-96  
By R. ROBINSON, DEPUTY  
File No. 074-1996R

GPO-591-971, 1988