
CERTIFIED RECORD OF LAND CORNER MONUMENTATION

by Jacob C. Cooper, unerr General Land Office Contract History of original corner establishment:

No. 397.
Surveyor General records (notes) states:
Set pine post 4 ft. long 3 ins. thick 2 ft. in ground for $\frac{1}{4}$ sec. cor.

Pine 20 in. dia. S 54° E, 159 lks. Pine 20 in. dia. N 32° W, 113 lks.

note: No restoration appears in the county records.



Description of corner evidence found:

Found 30 ins. Pond. Pine, Live & in good condition, with scribing visible, bearing S540E 105.0 ft. dist. from the corner position. Found uprooted pine, bearing approx. N320W 78 ft. from the corner position, no scribing visible. Established corner position N54°W 105.0 ft. dist. from live 30 ins. Pine.


Description of monument and accessories I established to perpetuate the original location of this corner

Set 30" $x2\frac{1}{2}$ " iron pipe with 3" brass cap marked as shown, 25" in the ground & raised a mound of stone arounde the pine.

From which a new Bearing Tree.
A Fir 16 ins. diam. bears N3 E, 107.5 ft. dist.
Marked T1S R36E 4S34 BT.

Distance taken to a brass washer in the blaze of the

new bearing tree.
Set a steel fence post approx. 5 ft. East from corner with forest boundry sigh attatched.



REGISTERED **PROFESSIONAL** AND SURVEYOR

OREGON JULY 12, 1968 DOUGLAS M. FERGUSON 848

Used a steel tape & magnetic compass with declination equal 20° East.

Office of	•	County of	
		that the within instrument wa	
***************************************	ICIAL)	hu	

Form R6-7100-57 (9/66)

	UNION COUNTY SURVEYOR	
	Date Received	
	Date Filed	
,	Ву	

File No. 224-884 R