


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

A-19
Z-19

History of original corner establishment: Corner established in 1882 by Herman D. Gradon, under General Land Office Contract No. 452.

Surveyor General Records (Notes) states:
Pine post 4' long 3" thick 2' in ground from which a pine 15" dia. bears N14°E 138 lks. dist.
A fir 20" dia. bears S14°W 75 lks.




(No subsequent remonumentations in county records)

Description of corner evidence found:

Found 24 in. ponderosa pine, live in good condition, marked 1/4 S, positioned 1/4 corner between Section 35 and 2, S14°W, 91 ft. dist. from notch in blaze.

Description of monument and accessories established to perpetuate the original location of this corner

Set 30 in. x 2 1/2 in. iron pipe with 3 in. brass cap marked as shown 6 in. in the ground to solid rock and chiseled an "X" in rock under pipe for the 1/4 Section Corner between Sections 35 & 4, and raised a mound of stone 4 ft. in diam. and 2 1/2 ft. high around the pipe, from which new BT's -
A 20 in. fir bears S60°W 86.9 ft. marked T2S R36E 1/4 S2 BT.
Measurement taken to a brass washer in face of blaze. Set steel fence post approximately 5 ft. west with warning sign attached.



Used steel tape and magnetic compass with declination = 20° East.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Douglas M. Ferguson
OREGON
JULY 12, 1968
DOUGLAS M. FERGUSON
848

Office of..... County of.....
State of....., I hereby certify that the within instrument was filed in this office
for record on the day of 19....., at..... o'clockm., (signed)
..... by
(COUNTY OFFICIAL) (DEPUTY)

UNION COUNTY
SURVEYOR
Date Received _____
Date Filed _____
By _____
File No. 225-84 R