## CER MED RECORD OF LAND CORNER MONUMENTAT N

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

Corner not established.

T 2 S R 36 E B - 03
S 6

 $\mathbf{D}\textsc{escription}$  of corner evidence found:

None.

See Survey Number 016-2011.

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED

TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At position determined by survey, I set a 5/8" x 30" iron pin with 2  $\frac{1}{2}$ " Aluminum cap, marked as shown below, from which:

A 13 inch Western Larch bears South 40° West, a distance of 13.65 feet, marked CN 1/16 S6 BT.

A 12 inch Western Larch bears North 52° West, a distance of 40.80 feet, marked CN 1/16 S6 BT.

I hereby certify that the corner was monumented on June 1, 2011.


Witness: Gregory T. Blackman Jr.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
June 2, 2010
JEFFERY S. HSU
83571

Renewal Date: June 30, 2011

UNION COUNTY SURVEYOR
Date Received 6/6/1)
Date Filed 6/23/1/
Filed By R. RUBINSON DEAVY
File Number 010-7011 R



I used a magnetic compass and steel tape in the establishment of the accessories. Magnetic declination used was  $16^{\circ}$  East. The distances are to a 60d spike in the right hand side of the trees and bearings are to a brass washer marked OPLS 83571 to the center of the BT blaze.