


**CERTIFIED RECORD OF LAND CORNER MONUMENTATION**

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:  
None

No record of subsequent monumentation found in  
Union County survey records



DESCRIPTION OF CORNER EVIDENCE FOUND:  
None

See Union County Survey Number 033-1997.

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED  
TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position determined by the survey I set a 2½"x30" aluminum pipe with  
aluminum cap marked as shown, 31 inches in the ground, (1 inch below the  
driveway surface), from which;


NEW BEARING TREES:

A 9" Tamarack bears N 33°18'E, 77.34 feet, marked N 1/16 S5 BT.

A 11" Lodgepole Pine bears N 87°31'W, 62.88 feet, marked N 1/16 S6 BT.

I hereby certify that the corner was monumented on November 7, 1997.  
Witness: Greg Blackman, Jr.

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR  
*Rick G Robinson*  
OREGON  
July 17, 1986  
RICK G. ROBINSON  
2219  
Renewal Date December 31, 1998



I used a total station instrument in the  
establishment of the new accessories. The  
basis of bearing is the same as survey number  
033-1997. The distances are to a 60d spike  
driven into the right side of the root crown  
of the bearing tree. I attached a brass  
washer marked OPLS 2219 to the BT blaze.

UNION COUNTY  
SURVEYOR  
Date Received 11/8/97  
Date Filed 11/8/97  
Filed By *Greg T. Blackman*  
File Number 056-1997R