CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not originally established

DESCRIPTION OF CORNER EVIDENCE FOUND:

None

See Survey No. 026-2015

S 4

T2S R36 EB-13

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position determined by survey, I set a 5/8" x 30" iron pin with a 2 ½" aluminum marked as shown, 30" in the ground. From which:

NEW BEARING OBJECTS:

An 8" Western Larch bears South 39° East, a distance of 28.05 feet, marked N 1/16 S3 BT. A 6" Ponderosa Pine bears South 65° West, a distance of 21.25 feet, marked N 1/16 S4 BT.

I set a steel fencepost approximately 1 foot North of corner monument.

I hereby certify that the corner was monumented on April 30, 2015.


Witness: Thomas J. Kopp


PROFESSIONAL
LAND SURVEYOR

OREGON
June 2, 2010

JEFFREY S. HSU
83571

Renewal Date: June 30, 2017





I used a steel tape and magnetic compass in the establishment of the new accessories. I used 16° East declination, the distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.