## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

E-1 E-25

History of original corner establishment:

Corner established by General Land Office contract survey
The original notes state;
North on west boundary of Section 7.
80.00 chains set a basalt stone 18x12x8, 8" in ground for corner of Sec. 6.7.1 and 12 from which;
Pine 20" in dia N35°W 38 lks. marked T2S R35E S1BT;
Pine 18" in dia N41°E 103 lks marked T2S R36E S6BT;
Fir 20" in dia S46°E 15 lks marked T2S R36E S7BT;
No other tree near.

| DIAGRAM | 1      |
|---------|--------|
| T       | 2S     |
| R35E    | R36EWM |
| 1       | 6      |
| 12      | 7      |

Description of corner evidence found: Pine stump 18" in dia N35°W 38 lks. with scribe; Fir stump 20" in diam S46°E 15 lks with scribe;

| UNIC       | ON COUNTY<br>URVEYOR |
|------------|----------------------|
| Date Rece  | ived                 |
| Date Filed |                      |
| Ву         |                      |
| File No.   | 228-84R              |

Description of monument and accessories I established to perpetuate the

wighted location of this corner
At the position of the corner I set a 30% pipe
with an eight inch plate welded to bottom and a
bronze cap on top. The hole was back filled with stone
and tamped soil

I stamped the cap

From the monument the original bearing trees are; (none) I established the following new bearing trees; A Ponderosa pine 12" in diam N41°W at distance of 31.2 ft. and scribed T2S, R35E S1 BT; A ponderosa pine 14" in diam N16°E at distance of 27.1 ft. scribed T2S, R36E, S6 BT; A ponderosa pine 12" in diam S46°E a distance of 27.1 ft.

| T2    | · · · · · · · · · · · · · · · · · · · |
|-------|---------------------------------------|
| R35E  | R36E                                  |
| 31    | <b>s</b> 6                            |
| 512   | 57                                    |
| ORE L | IC 381<br>70                          |

A ponderosa pine 12" in diam S46°E a distance of 27.4 ft.
scribed T23, R36E, S7, BT;
A ponderosa pine 10" in diam S54°W at distance of 9.4 ft. scribed T28, R35E, S12BT;
The distance measured to center of respective trees on level. I placed bearing tree signs on both old and new bearing trees and painted stripe around trees
I placed a steel fence post with USFS sign 54-4 attached.near the corner.

| Office of County surveyor   | County of Union                      |                |
|---|--------------------------------------|----------------|
| for record on the   | that the within instrument was filed | in this office |
| State of Oregon , I hereby certify a for record on the 18 day of July  County Sruve yor b | DEPUTY)                              | (Signed)       |