
CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

No record of subsequent monumentation found in Union County survey records

DESCRIPTION OF CORNER EVIDENCE FOUND: None

See Union County Survey Number 043-1995.



DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED At the position determined by the survey I set a 2½"x30" aluminum pipe with aluminum cap marked as shown, 12 inches in the ground with a mound of stones 3 feet base to top of cap, from which;

NEW BEARING TREES:

A 9" Tamarack bears N7°E, 56.10 feet, marked E 1/16 S6 BT.

A 16" Ponderosa Pine bears S17°E, 73.12 feet, marked E 1/16 S7 BT.

I hereby certify that the corner was monumented on October 24, 1995. Mark Durbin, Jeff Madsen Witness:

> REGISTERED **PROFESSIONAL** LAND SURVEYOR etimo OREGON JEFFERY P. PETERSEN 2625 Romawal Date: December, 31 1996

T28 R36E 86 E 1/16 87 1995 2625 OPLS

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 18° East declination, the distances are to a 60d spike driven into the right side of the root crown of the bearing tree.

UNION COUNTY **SURVEYOR** Date Received 11-13-95 11-13-95 File Number 636-1995 R