

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

G-1

History of original corner establishment:


Corner established in 1873 by John A. Hurlburt under Government Land Office contract number 201.

Surveyor General record states

Set pine post for 1/4 section corner from which:

A pine 6 in. dia. S62W, 12 links

A pine 8 in. dia. S24E, 8 links



No record of subsequent remonumentation was found in county records.

Description of corner evidence found:

NONE

See map of survey dated 5/19/80


Description of monument and accessories I established to perpetuate the original location of this corner:

At proportionate distance I set a 2 1/2 inch x 30 inch iron post with brass cap marked as shown, 24 inches in the ground from which:

NEW BTs

A 6 inch Tamarack bears N46E, 36.3 feet marked X BT

A 22 inch Tamarack bears N44W, 144.8 feet marked 1/4 S12 BT



REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

OREGON  
JULY 12, 1984  
DUANE L. GRIFFITH  
844

Brass washer nailed to B.T. blaze.  
Used steel tape and magnetic  
compass with 20° East declination  
Measured to center of B.T.s

Office of..... County of.....

State of..... I hereby certify that the within instrument was filed in this office

for record on the..... day of....., 19.....

..... by .....  
(COUNTY OFFICIAL) (DEPUTY)

UNION COUNTY  
SURVEYOR

Date Received \_\_\_\_\_

Date Filed \_\_\_\_\_

By \_\_\_\_\_

File No. 235-84R