


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. G-7

History of original corner establishment:

Not established during original survey




Description of corner evidence found:

None

Description of monument and accessories established to perpetuate the original location of this corner:

Corner location determined by survey and subdivision of Section 8. At surveyed point set 2 1/2"x30" galvanized pipe with brass cap stamped:



Set pipe 14" in ground with mound of stone to cap.

Bearing trees:

A P. Pine 18" dia. bears N20° E, 3.7 ft. scribed C 1/4 S8 BT.
A Douglas Fir 14" in dia. bears S69°W, 49.5 ft. scribed C 1/4 S8 BT.

Attached 54-3 and 54-4 signs to both BT's and brass washer stamped LS 1099 to foot blaze of both BT's. Painted blazes and 6" band around both BT's red. Attached 54-2, 54-4, and 54-9 signs to metal post 5 feet north of corner. Corner falls on S.W. slope at South edge of large clearing and 88 ft. West of N-S fence.

Compass Declination: 18 1/2° East.

I hereby certify the above described corner monument and/or accessories was established on October 4, 1981.

Witnesses: Rodger Orton
Jeff Anderson



Office of.....Surveyor..... County of..... Union.....
State of.....Oregon..... I hereby certify that the within instrument was filed in this office
for record on the.....4..... day of.....OCTOBER....., 1981
Howard L. Perry..... by Gary L. Langlitz
(COUNTY OFFICIAL) (DEPUTY)

UNION COUNTY SURVEYOR

Date Received _____

Date Filed _____

By _____

File No. 241-84 B