


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index No. H-6

History of original corner establishment:

Not established during original survey




Description of corner evidence found:

None

Description of monument and accessories established to perpetuate the original location of this corner:

Corner location by survey and subdivision of Section 8.

At surveyed point set 2 1/2" x 30" galvanized pipe with brass cap stamped:



Set pipe 22" in ground with mound of stones and dirt to cap.

Bearing trees:

OR PLS 1099

A grand fir 10" dia. bears S4°E, 13.7 ft. scribed SW 1/16 S8 BT.
A Tamarack 10" dia. bears S75° W., 37.9 ft. scribed SW 1/16 S 8 BT.

Attached 54-3 and 54-4 signs to both BT's and brass washer stamped LS 1099 to foot blaze of both BT's. Painted blazes and 6" band around both BT's red. Attached 54-2, 54-4 and 54-9 signs to metal post 5 ft. North of Cor. and 54-2 sign to metal post 5 ft. East of Cor. Corner falls in bottom of draw, course N.E.

Compass Declination: 18 1/2° East

I hereby certify the above described corner monument and/or accessories was established on October 14, 1981.

Witnesses: Rodger Orton
Jeff Anderson



Surveyor _____ County of _____ Union _____
 Office of _____
 State of _____, I hereby certify that the within instrument was filed in this office
 for record on the 4 day of OCTOBER, 1982
 Howard L. Perry _____ by Gary L. Langlitz
 (COUNTY OFFICIAL) (DEPUTY)

**UNION COUNTY
SURVEYOR**

Date Received _____

Date Filed _____ GPO 789-509

By _____

File No. 245-84 R