


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. H-7

History of original corner establishment:

Not established during original survey.



Description of corner evidence found:

None

Description of monument and accessories established to perpetuate the original location of this corner:

Corner location determined by survey and subdivision of Section 8. At surveyed point set 2 1/2" x 30" galvanized pipe with brass cap stamped:

Set pipes 15" in ground to rock with mound of stone and dirt to cap.

Bearing trees: A Lodgepole Pine 6" in dia. bears S82°E, 78.1 ft. scribed CS 1/16 S 8 BT.


A Douglas Fir 13" dia. bears S62° W, 76.3 ft. scribed CS 1/16 S 8 BT.

Attached 54-3 and 54-4 signs to both BT's and brass washer stamped LS 1099 to foot blaze of both BT's. Painted blazes and 6" band around both BT's red. Attached 54-2, 54-4 and 54-9 signs to metal post 5 ft. north of Cor. Attached 54-2 sign to metal post 5 ft. west of Cor. Corner falls on level ground 14 ft. East of N-S fence and 35 ft. South of centerline of existing power lines running SE and NW.

Compass Declination 18 1/2° East.

I hereby certify the above described corner monument and/or accessories was established on October 14, 1981.

Witnesses: Rodger Orton
Jeff Anderson



Office of..... Surveyor..... County of..... Union.....
 State of..... Oregon..... I hereby certify that the within instrument was filed in this office
 for record on the 4 day of OCTOBER..... 1982
 Howard L. Perry by Gary L. Langlitz
 (COUNTY OFFICIAL) (DEPUTY)

UNION COUNTY SURVEYOR

Date Received _____

GPO 799-509

Date Filed _____

By _____

File No. 246-84 B