


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. L-2

History of original corner establishment:

Not established during original survey



Description of corner evidence found:

None

Description of monument and accessories I established to perpetuate the original location of this corner:

Corner Location determined by survey and subdivision of Section 18.

At surveyed point: set 2 1/2"x30" galvanized pipe with brass cap attached 15" in the ground stamped:

Built mound of stone and dirt to cap.

From which:

An 8" Ponderosa Pine bears N 1°W 38.3 ft. scribed CW 1/16 S 18 BT.

An 8" Douglas Fir bears N66°E 15.0 ft. scribed CW 1/16 S18 BT.


Attached 54-3 and 54-4 signs to BT's. Planted blazes and 6" red ring around trees. Attached brass washers LS 1099 to foot blazes. Set metal post 5 ft. north of corner with 54-2, 54-4, and 54-9 signs.

Corner falls on level ground 10 ft. east of dirt road.

Compass Declination: 18 1/2° East

I hereby certify the above described corner monument and/or accessories was established as described on November 13, 1981.

Witnesses: Loren Huntsman
Millard Wyatt



Office of..... Surveyor..... County of..... Union.....
 State of..... Oregon....., I hereby certify that the within instrument was filed in this office
 for record on the... 4... day of... OCTOBER... 1982...
 Howard L. Perry..... by *Gary L. Langlitz*.....
 (COUNTY OFFICIAL) (DEPUTY)

UNION COUNTY SURVEYOR

Date Received _____
 ☆ GPO-799-276

Date Filed _____

By _____

File No. 254-84R