


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. L-3

History of original corner establishment:

Not established during original survey



Description of corner evidence found:

None

Description of monument and accessories established to perpetuate the original location of this corner:

Corner location determined by survey and subdivision of Section 18.

At Surveyed Point set 2 1/2" x 30" galvanized pipe with brass cap attached 24 inches in the ground stamped:

T2S R36E
 C1/4 S18
 1981
 OR PLS 1099

From which:

A 16" White Fir bears S75°W 7.1 ft. scribed
C 1/4 S18 BT

A 9" White Fir bears N 52°E 26.0 ft. scribed: C 1/4 S18 BT.

Attached 54-3 and 54-4 signs to BT's. Painted blazes and 6" red ring around BT's. Attached brass washers LS 1099 to foot blazes. Set metal post 5 ft. north of corner with 54-4 and 54-9 sign.

Corner falls on level ground 100 ft. east of NE draw and 250 ft. east of dirt road.

Compass Declination: 18 1/2° East

I hereby certify the above described corner monument and/or accessories was established as described on November 16, 1981.

Witnesses: Loren Huntsman
Millard Wyatt



Office of..... Surveyor..... County of..... Union.....
 State of..... Oregon....., I hereby certify that the within instrument was filed in this office
 for record on the... 4... day of... OCTOBER....., 1982.
 Howard L. Perry..... by *Gary L. Langlitz*
 (COUNTY OFFICIAL)..... (DEPUTY)

