


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. L-4

History of original corner establishment:

Not established during original survey



Description of corner evidence found:

None

Description of monument and accessories established to perpetuate the original location of this corner:

Corner location determined by survey and subdivision of Section 18:

At surveyed point: Set 2 1/2" x 30" galvanized pipe with brass cap attached 24" in the ground stamped:

T2S R36E
 E 1/16
 C—|—C
 S18
 1981
 OR PLS 1099

From which:

A 12" Douglas Fir bears N 84° W 27.4 ft. scribed
 CE 1/16 S18 BT
 A 6" Douglas Fir bears S19°W 26.9 ft. scribed
 CE 1/16 S18 BT

Attached 54-3 and 54-4 signs to BT's. Painted blazes and 6" red ring around BT's. Attached brass washers LS 1099 to foot blazes. Set metal post 5 ft. East of Corner with 54-2 and 54-4 signs. Set metal post 5 ft. South of corner with 54-2 and 54-9 signs.

Corner falls in pole thicket 140 ft. west of old dead end road.

Compass Declination: 18 1/2° East

I hereby certify the above described corner monument and/or accessories was established as described on November 17, 1981.

Witnesses: Loren Huntsman
Millard Wyatt
Union

Office of..... Surveyor..... County of.....
 Oregon.....
 State of....., I hereby certify that the within instrument was filed in this office
 for record on the 4 day of OCTOBER, 1982.
 Howard L. Perry..... by Gary L. Langlitz
 (COUNTY OFFICIAL)..... (DEPUTY)

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

Gary L. Langlitz
OREGON
 JULY 22, 1977
GARY L. LANGLITZ
 1089

**UNION COUNTY
SURVEYOR**

Date Received _____
 ☆ GPO—798-276
 Date Filed _____
 By _____
 File No. 256-84R