## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

## History of original corner establishment:

In 1895 Marcius Buchanan, under GLO Contract No. 635 set a Tamarack post 3 ft. long 3" sq. 24 inches in ground for 1/4 cor marked 1/4 S on West face from which

A Pine 7" in dia. bears N54° W 32 1/2 lks. marked 1/4 S BT. A Pine 4" in dia. bears S 81° E 32 lks. marked 1/4 S BT.

Remonumentation by Bureau of Land Management, 1975:

The 1/4 Sec. Cor. of Secs. 17 and 18, determined at record distance from the original bearing trees:

A Pine, 11 ins. diam. bears S. 86° E., 32 lks. dist.,

with healed blaze (Record, S. 81°E).

A Pine, 11 ins. diam., bears N 54° W., 32 1/2 lks. dist., with scribe marks 1/4 S. BT visible on partially healed blaze. At the corner point set an iron post, 28 ins. long, 2 1/2 ins. diam.

24 ins. in the ground, with brass cap marked:

Index File No. L-5 DIAGRAM T2S **R36E** 17 18

T 2 S R 36 E 1/4 S18 | S17 1975

Description of corner evidence found: FOUND: 2 1/2" Iron Pipe with cap 20" in ground stamped

Both original BT's still standing but now dead: A 12"

Pine bears N54°W 21.5 ft. with a healed blaze.

A 12" Pine bears S81°E 21.1 ft. visible scribing "1/4 S BT"

Bureau of Land Management T2S R36E 1/4 S18 S17 1975

## Description of monument and accessories I established to perpetuate the original location of this corner:

We establish new BT's as follows:

A Douglas Fir 13" in dia. bears N49° W 12.3 ft. scribed 1/4 S18 BT

A Douglas Fir 7" in dia. bears S38°E 28.9 ft. scribed 1/4 S 17 BT.

Attached brass washers PLS 1099 to new BT's. Attached all signs and painted all trees according to Standard Specification for Cadastral Survey USFS Region 6, Oct. 1979.

Compass Declination: 18 1/2° East

I hereby certify the above described corner monument and/or accessories was established as described on July 1, 1981.

> Witnesses: Loren Huntsman Millard Wyatt

REGISTERED **PROFESSIONAL** LAND SURVEYOR

OREGON GARY L. LANGLITZ 1009

Office of Surveyor	County of	•••••
state of Oregon I hardy	months that the solthin landauman and some differe	In this office
for record on the day of O.C.T.98	ER	
Howard L. Perry	by Dan I doubt	UPHON C
(COUNTY OFFICIAL)	C VIDERVITY	208AE

Form R6-7100-57 (9/71)

CUNTY YOR Onto Received 20-798-276 To filed

Remonumentation of Certain Original Corner Points, T. 2 S., R. 36 E., Willamette Meridian, Oregon

CHAINS

A pine, 27 ins. diam., bears N. 31½° W., 104 lks. dist., mkd. ½ S17 BT.

Deposit corner stone alongside iron post.

The  $\frac{1}{4}$  sec. cor. of secs. 18 and 19, determined at record bearing and distance from the remains of the original bearing trees:

A root hole, bears S. 27° W., 41 lks. dist., with a down and decayed western larch stump alongside, 12 ins. diam., no marks visible.

A room hole, bears N. 31° W., 81 lks. dist., with a down and decayed western larch snag alongside, 18 ins. diam., with scribe marks BT whelble on decayed blaze.

At the corner point

Set an iron post, 28 ina, long  $2^{\frac{1}{2}}$  ins. diam., 24 ins. in the ground, with brass cap mkd.

2 S R 36 E 1<sub>4</sub> S R S 19 1975

from which new bearing trees

A pine, 10 ins. diam., bears N. 64½ E., 61½ lks. dist., mkd. ½ S18 BT.

A fir, 12 ins. diam., bears S. 15° W., 35 lks. dist., mkd. ½ S19 BT.

(Remonumenting corners established by Manius Buchanan, Deputy Surveyor, in 1895)

The  $\frac{1}{4}$  sec. cor. of secs. 17 and 18, determined at record distance from the original bearing trees:

A pine, 11 ins. diam., bears S. 86° E., 32 lks. dist., with healed blaze. (Record, S. 81° E.)

A pine, 11 ins. diam., bears N. 54° W., 32½ lks. dist., with scribe marks ½ S BT visible on partially healed blaze.

At the corner point

Set an iron post, 28 ins. long,  $2^{l_2}$  ins. diam., 24 ins. in the ground, with brass cap mkd.

T 2 S R 36 E S 18|S 17 1975

The k sec. cor. of secs. 8 and 17, determined at reord bearing and distance from the remains of the original bearing trees:

## UNION COUNTY SURVEYOR

Date Received 3/15/13

Date Filed 3/15/

By Off & L DEPUTY

File No. 340-2013R