


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. L-6

History of original corner establishment:

Not established during the original survey.



Description of corner evidence found:

None

Description of monument and accessories I established to perpetuate the original location of this corner:

Corner location determined by survey and subdivision of Section 17.

At surveyed point set 2 1/2" x 30" galvanized pipe 10" in the ground stamped:

Built a stone and dirt mound to cap.

Bearing trees:

A 10" P. Pine bears N34°E 23.6' scribed CW 1/16 S17 BT.


A 10" P. Pine bears S73°E 36.8 ft. scribed CW 1/16 S17 BT.

Attached 54-2 and 54-4 signs to BT's and brass washers LS 1099 to foot blazes. Painted blazes and 6" ring around BT's. Set a metal fence post 5' South of corner with a 54-2 sign. Another fence post is 5' west with 54-2, 54-4, 54-9 signs. Corner falls 6' east of steep cut for old Highway 30 and 38' east of highway.

Compass Declination: 18 1/2° East

I hereby certify the above described corner monument and/or accessories was established on October 22, 1981.

Witnesses: Loren Huntsman
Millard Wyatt



Office of..... Surveyor..... County of..... Union.....
 State of..... Oregon....., I hereby certify that the within instrument was filed in this office
 for record on the... 4... day of... OCTOBER....., 19.82
 .. Howard L. Perry..... by *Gary L. Langlitz*
 (COUNTY OFFICIAL) (DEPUTY)

UNION COUNTY SURVEYOR

Date Received _____

Date Filed ☆ GPO 799-509 _____

By _____

File No. 258-84R