


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Not established during original survey

Index File No. 1-7



Description of corner evidence found:

None

Description of monument and accessories established to perpetuate the original location of this corner:

Corner location determined by survey and subdivision of Section 17.

At surveyed point:

T2S R36E

Set 2 1/2"x30" galvanized pipe with brass cap stamped:
Pipe is set 24" in the ground with a dirt mound to cap.

C 1/4 | S17

1981

Bearing trees:

OR PLS 1099

A 7" White Fir bears S34°E 18.2' scribed C 1/4 S17 BT.
A 12" White Fir bears N53°W 24.8' scribed C 1/4 S17 BT.

Attached 54-3 and 54-4 signs to both BT's and brass washer LS 1099 to foot blazes. Painted blazes and 6" ring around BT's. Set a metal post 5' North of Cor. with 54-4 and 54-9 facing Cor. Corner falls on level ground S 65' North of SE-NW road.

Compass Declination: 18 1/2° East.

I hereby certify the above described corner monument and/or accessories was established on October 22, 1981.

Witnesses: Loren Huntsman
Millard Wyatt

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

Gary L. Langlitz

OREGON
JULY 22, 1977
GARY L. LANGLITZ
1099

Office of... Surveyor..... County of... Union.....

State of... Oregon..... I hereby certify that the within instrument was filed in this office

for record on the... 4... day of... OCTOBER..... 1982.

Howard L. Perry..... by *Gary L. Langlitz*.....
(COUNTY OFFICIAL) (DEPUTY)

**UNION COUNTY
SURVEYOR**

Date Received _____

Date Filed _____ GPO 799-509

By _____

File No. 259-84 R