


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. M-2

History of original corner establishment:

Not established during original survey



Description of corner evidence found:

None

Description of monument and accessories established to perpetuate the original location of this corner:

Corner location determined by survey and subdivision of Section 18:

At surveyed point: Set 2 1/2" x 30" galvanized pipe with brass cap attached 10" in the ground stamped:

T2S R36E
 SW1/16 S18
 1981
 OR PLS 1099

Built mound of stone and dirt to cap

From which: A 19" Ponderosa Pine bears S82°E 69.9 ft.

scribed SW 1/16 S 18 BT.

A 16" Douglas Fir bears N64°E 85.7 ft. scribed SW 1/16 S 18 BT.

Attached 54-3 and 54-4 signs to BT's. Painted blazes and 6" red ring around BT's. Attached brass washers LS 1099 to foot blazes. Set metal post 5 ft. north of corner with 54-2 and 54-4 signs. Set metal post 5 ft. East of corner with 54-2 and 54-9 signs.

Corner falls on bald west slope 185 ft. west of dirt road.

Compass Declination: 18 1/2° East

I hereby certify the above described corner monument and/or accessories was established as described on November 16, 1981.

Witnesses: Loren Huntsman
Millard Wyatt

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

Gary L. Langlitz
OREGON
JULY 22, 1977
GARY L. LANGLITZ
1099

Office of..... Surveyor..... County of..... Union.....

State of..... Oregon....., I hereby certify that the within instrument was filed in this office

for record on the 4 day of OCTOBER, 1982

Howard L. Perry by *Gary L. Langlitz*
(COUNTY OFFICIAL) (DEPUTY)

**UNION COUNTY
SURVEYOR**

Date Received _____
 ☆ GPO—798-276

Date Filed _____

By _____

File No. 261-84R