


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. M-3

History of original corner establishment:

Not established during original survey.



Description of corner evidence found:

None

Description of monument and accessories I established to perpetuate the original location of this corner:

Corner location determined by survey and subdivision of Section 18. At surveyed point set 2 1/2" x 30" galvanized pipe with brass cap attached 24 " in ground stamped:

T2S R36E

From which:

S 1/16 S18

A 10" White Fir bears S20°E 7.5 ft. scribed CS 1/16 S18 BT.

C  
1981  
ORPLS 1099

A 14" Douglas Fir bears N13°E 22.9 ft. scribed CS 1/16 S18 BT.


Attached 54-3 and 54-4 signs to BT's. Painted blazes and 6" red ring around BT's. Attached brass washers LS 1099 to foot blazes. Set metal fence post 5' South with 54-2 and 54-9 signs. Set metal post 5' west with 54-2 and 54-4 signs.

Corner falls on east slope 45' east of small clearing and 30' north of BLM blaze line.

Compass Declination: 18 1/2° East.

I hereby certify the above described corner monument and/or accessories was established as described on November 13, 1981.

Witnesses: Loren Huntsman  
Millard Wyatt



Office of..... Surveyor..... County of..... Union.....  
 Oregon  
 State of....., I hereby certify that the within instrument was filed in this office  
 for record on the 4 day of OCTOBER, 1982.  
 Howard L. Perry by Gary L. Langlitz  
 (COUNTY OFFICIAL) (DEPUTY)

UNION COUNTY  
SURVEYOR

Date Received \_\_\_\_\_  
 Date Filed \_\_\_\_\_  
 By \_\_\_\_\_  
 File No. 262-84R