


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Not established during original survey.

Index File No. N-2



Description of corner evidence found:

None

Description of monument and accessories I established to perpetuate the original location of this corner:

Corner location determined by survey and single proportionate measurement between the N 1/4 and NW corner of Section 19.

At Surveyed Point:

Set 2 1/2" x 30" galvanized pipe 4" in the ground with brass cap attached stamped:

Built mound W 1/16 of stone and dirt to cap.

From which:

A 15" Douglas Fir bears S36°W 148.3 ft. scribed
W 1/16 S 19 BT.

A 12" Douglas Fir bears N 89°W 100.6 ft. scribed
W 1/16 S18 BT


Attached 54-3 and 54-4 signs to BT's. Painted red ring around BT's and painted blazes. Set metal post 5' north of corner with 54-4 and 54-9 signs attached.

Compass Declination: 18 1/2° East

	T2S	R36E
	$\frac{1}{16}$	$\frac{S18}{S19}$
		1981
		OR PLS 1099

I hereby certify the above described corner monument and/or accessories was established as described on November 16, 1981.

Witnesses: Loren Huntsman
Millard Wyatt



Office of..... Surveyor..... County of..... Union.....
 State of..... Oregon..... I hereby certify that the within instrument was filed in this office
 for record on the... 4... day of... OCTOBER... 1982.
 Howard L. Perry..... by *Gary L. Langlitz*.....
 (COUNTY OFFICIAL) (DEPUTY)

UNION COUNTY SURVEYOR	
Date Received	_____
Date Filed	_____
By	_____
File No.	<u>266-84 R</u>