CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:			Index File No. N-4
			DIAGRAM
Not established during original survey.			T2S R36E
			E1/16 ————
			19
Description of corner evidence found:			
None			
· · · · · · · · · · · · · · · · · · ·			
Description of monument and accessories I established	d to perpetuate t	the	
original location of this corner:			
Corner location determined by survey and between the N1/4 and NE corner of Section	n 19:		S18
At surveyed point set $2\frac{1}{2}$ "x30" galvanized 24" in the ground stamped:	pipe with b	rass cap atta	ached E1/16—+
From which:			1981 OR PLS 1099
A 13" Tamarack bears N48 ⁰ W, 25.0 Ft. scr A 12" Doug. Fir bears S43 ⁰ W, 24.8 Ft. sc	ribed E1/16	218 RI.	
Attached 54-3 & 54-4 signs to BT's. Pai brass washers LS 1099 to foot blazes. S 54-2 & 54-4 signs. Set metal fence post	er merai ten	ICA nact & Et	Couth of communities
Corner falls on West slope 40 Ft. North	of East-West	draw.	•
	Compass Dec	:lination: 18	3½° East
	monument an	rtify the abo d/or accessor d on Nov. 13,	ove described corner ries was established - 1981
		Loren Huntsm	man
	•	Millard Wyat	
			Gronn.
			Jan J. Kanglit
			OREGON C
Office of Surveyor Co	ounty of	Union	GARY L. LANGLITZ 1099
State of Oregon , I hereby certify that if	the within instrum	ent was filed in thi	s office
for record on the A day of OCTOBER Howard L. Perry	1952 J	0 -4	UNION COUNTY
(COUNTY OFFICIAL)		ANGREETY)	SURVEYOR

Form R6-7100-57 (9/71)