


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Not established during original survey

Index File No. N-6



Description of corner evidence found:

None

Description of monument and accessories established to perpetuate the original location of this corner:

Corner location determined by single proportionate measurement between the North 1/4 and NW corner of Section 20.


At surveyed point set 2 1/2"x30" galvanized pipe with brass cap stamped:

Set pipe 18" in ground and built mound of dirt and stone to cap

Bearing trees:

An 11" White Fir bears N39°E 21.7 ft. scribed W 1/16 S17 BT.

An 11" White Fir bears S 58°W 9.8 ft. scribed W 1/16 S20 BT.



Attached 54-3 and 54-4 signs to both BT's and brass washer LS 1099 to foot slope. Painted blazes and 6" ring around BT's. Att. 54-2, 54-4 & 54-9 signs to metal fence post 5' west of corner. Corner falls on NE slope about 6.3 ft. North of SW-NE intermittent stream bed.

Compass Declination: 18 1/2° East.

I hereby certify the above described corner monument and/or accessories was established on October 19, 1981.

Witnesses: Loren Huntsman
Millard Wyatt



Office of..... Surveyor..... County of..... Union.....
 State of..... Oregon..... I hereby certify that the within instrument was filed in this office
 for record on the 4 day of OCTOBER..... 1982
 Howard L. Perry by Gary L. Langlitz
 (COUNTY OFFICIAL) (DEPUTY)

UNION COUNTY SURVEYOR

Date Received _____

Date Filed _____

By _____

File No. 269-84R