


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. N-8

History of original corner establishment:

Not established during original survey.



Description of corner evidence found:

None

Description of monument and accessories established to perpetuate the original location of this corner:

Corner location determined by single proportionate measurement between the South 1/4 and SE corner of Section 17.

At surveyed point

Set 2 1/2" x 30" galvanized pipe with brass cap attached 24" in the ground stamped:

T2S	R36E
S17	
E 1/16	—+—
S20	
1981	
OR PLS 1099	

From which:

A 10" Tamarack bears S70°W 4.7 ft. scribed E 1/16 S20 BT


An 11" Douglas Fir bears N 89°E 76.2 ft. scribed E 1/16 S17 BT.

Attached 54-3 and 54-4 signs to BT's. Painted blazes and red ring around BT's. Attached brass washers LS 1099 to foot blaze. Set metal post 5 ft. north of corner with 54-4 and 54-9 signs.

Corner falls on slight NW slope in small Pine & Tamarack 260 ft. east of fork in old dirt road.

Compass Declination: 18 1/2° East

I hereby certify the above described corner monument and/or accessories was established as described on November 9, 1981.



Witnesses: Loren Huntsman  
Millard Wyatt

Surveyor \_\_\_\_\_ Office of \_\_\_\_\_ County of \_\_\_\_\_ Union  
 State of \_\_\_\_\_ Oregon \_\_\_\_\_ I hereby certify that the within instrument was filed in this office  
 for record on the 4 day of OCTOBER, 1982  
 Howard L. Perry \_\_\_\_\_ by Gary L. Langlitz  
 (COUNTY OFFICIAL) (DEPUTY)

<b>UNION COUNTY SURVEYOR</b>	
Date Received _____	GPO 799-509
Date Filed _____	
By _____	
File No. <u>270-84 R</u>	