

27-10A  
37-70A

CERTIFIED RECORD OF LAND CORNER MONUMENTATION


N-9

History of original corner establishment:

Corner established by General Land Office contract survey

The original notes state:

52.50 top of ridge and old road. Run SE  
80.00 Set fir post 4 ft. long 4 in. square, 2' in ground for corner to Sections 16, 17, 20, and 21, from which  
Tamarack 10" dia N39°W 25 lks marked T2S R36E S17BT;  
Tamarack 15" dia S71°W 17 lks marked T2S R36E S20BT;  
Pine 6" dia S65°E 40 lks marked T2S R36E S21BT;  
Fir 10" dia N64°E 36 lks marked T2S R36E S16BT;  
Land broken. Soil was 1st to 3rd rate. Pine, Tamarack and Fir timber. Some grass.



Description of corner evidence found:

Rotten stump ~~with~~ scribe. No other evidence was found.

Description of monument and accessories I established to perpetuate the original location of this corner:

At the position of the corner I set a 30" galvanized pipe with an eight inch plate welded to the bottom and a bronze cap on top. The hole was back filled with stone and tamped soil.

I stamped the disk.

From the monument the original bearing trees were; (none). I established the following new bearing trees;

Lodge Pole Pine 15" dia, N4°W at a distance of 8.3 ft. and scribed T2S R36E S17 BT.


Tamarack 12" dia, N84°E at a distance of 26.6 ft. and scribed T2S R36E S16 BT

White Fir 9" dia, S24°W at a distance of 57.7 ft. and scribed T2S R36E S20 BT

Tamarack 11" dia, S59°E at a distance of 36.4 ft. and scribed T2S R36E S21 BT.

The distance measured to center of respective trees on level. I placed bearing tree sign on both old and new bearing trees and painted stripe around the trees.

I placed a steel post with USFS sign 54-4 attached near the corner, also sign indicating private land to the west and USFS land to the east.



Office of County Surveyor County of Union  
State of Oregon, I hereby certify that the within instrument was filed in this office for record on the 25th day of August, 1970, at 5 o'clock P.m., (signed)  
County Surveyor by [Signature]  
(COUNTY OFFICIAL) (DEPUTY)

**UNION COUNTY SURVEYOR**

Date Received \_\_\_\_\_

Date Filed \_\_\_\_\_

By \_\_\_\_\_


File No. 271-84B

CERTIFIED RECORD OF LAND CORNER MONUMENTATION


**History of original corner establishment:**

In 1874 under GLO Contract No. 201, John A. Hurlburt set Fir Post 4 ft. long 4 in. square 2 feet in the ground for Cor to Sec. 16, 17, 20, 21. From which: Tamarack 10" diameter N39°W 25 lks. marked T2S R36E S17 BT.  
Tamarack 15" dia. S71 W 17 lks. marked T2S R36E S20BT  
Pine 6" dia. S65°E 40 lks marked T2S R36E S21 BT.  
Fir 10" dia. N64° E 36 lks. marked T2S R36E S16 BT.

Index File No. N-9




Remonumentation by J. Voelz, LS 381, 1970 per Union Co. Records:  
FOUND: Rotten Stump. No other evidence was found. At the position of the corner I set a 30" galvanized pipe with an eight inch plate welded to the bottom and a bronze cap on top. The hole was backfilled with stone and tamped soil. I stamped the disk:



**Description of corner evidence found:**

FOUND: 2" Iron Pipe with cap set 18" in ground, stamped



**BT's Set in 1970 (Voelz)**

Tamarack 13" dia. N84°E 26.6 ft. with visible scribing T2S R36E S16 BT  
Dead Tamarack 12" dia. S59°E 36.4 ft. with visible scribing T2S R36E S21 BT  
White Fir 10" dia. S24°W 57.7 ft. with visible scribing S20 BT.  
15" Lodgepole Pine, down, bears N4°W 8.3 ft., scribing "T2S R" visible.

**Description of monument and accessories I established to perpetuate the original location of this corner:**

We mark new BT's as follows:

- An 8" White Fir bears S54 E 41.4 ft. scribed T2S R36E S21 BT
- A Douglas Fir 8" dia. bears N9°W 38.0 ft. scribed T2S R36E S17 BT.

Attached brass washer in foot blaze of both new trees PLS 1099. Attached signs and painted old and new BT's per standard specification for cadastral survey USFS Reg. 6 Oct. 1970.

Compass Declination: 18 1/2° East

I hereby certify the above described corner monument and/or accessories was established on July 1, 1981.

Witnesses: Loren Huntsman  
Millard Wyatt



Office of.....Surveyor..... County of..... Union.....  
State of..... Oregon..... I hereby certify that the within instrument was filed in this office  
for record on the...4... day of...OCTOBER..... 1982  
.....Howard L. Perry..... by..... Gary L. Langlitz.....  
(COUNTY OFFICIAL) (DEPUTY)

**UNION COUNTY SURVEYOR**

Date Received \_\_\_\_\_

Date Filed \_\_\_\_\_ GPO-798-276

By \_\_\_\_\_

File No. 272-84 R

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Page 2 of 2  
INDEX FILE No. N-9

**History of original corner establishment:**

From the monument the original bearing trees were: (none).

I established the following new bearing trees:

Lodge Pole Pine 15" dia. N 4° W at a distance of 8.3 ft. and scribed T2S R36E S17 BT.

Tamarack 12" dia. N 84°E at a distance of 26.6 ft. and scribed T2S R36 E S16 BT.

White Fir 9" dia. S24°W at a distance of 57.7 ft. and scribed T2S R36E S20 BT.

Tamarack 11" dia. S59°E at a distance of 36.4 ft. and scribed T2S R36E S21 BT.

The distance measured to center of respective trees on level. I placed bearing tree sign on both old and new bearing trees and painted stripe around the trees. I placed a steel post with USFS 54-4 attached near the corner, also sign indicating private land to the west and USFS land to the east.

**Description of corner evidence found:**

**Description of monument and accessories I established to perpetuate the original location of this corner:**

Office of..... County of.....

State of....., I hereby certify that the within instrument was filed in this office

for record on the..... day of....., 19.....

..... by .....

(COUNTY OFFICIAL)

(DEPUTY)

**UNION COUNTY  
SURVEYOR**

Date Received \_\_\_\_\_  
R O P O - 788-276

Date Filed \_\_\_\_\_

By \_\_\_\_\_

File No. 272-84 R