


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Not established during original survey.

Index No. 0-1



Description of corner evidence found:

None.

Description of monument and accessories established to perpetuate the original location of this corner:

Corner location determined by single proportionate measurement between the W 1/4 and NW corner of Sec. 19, T2S, R36E:

At surveyed point:

Set 2 1/2"x30" galvanized pipe with brass cap attached 12" in the ground stamped:

Built mound of stone and dirt to cap.

From which:

An 8" Doug. Fir bears S81°E 12.1 ft., scribed N 1/16 S19 BT.

A 22" Doug. Fir bears S67°W 14.0 ft., scribed N 1/16 S24 BT.

Attached 54-3 and 54-4 signs to BT's. Painted blazes and red 6" ring around BT's. Attached brass washers LS 1099 to foot blazes. Set metal fence post 5' west of corner with 54-2, 54-4 and 54-9 signs.

Corner falls on east slope 150' west from bottom of wet weather stream 200' north of another wet weather stream and 225' east of dead end on dirt road.


Compass Declination: 18 1/2° East.

I hereby certify the above described corner monument and/or accessories was established as described on Nov. 10, 1981.

Witnesses: Loren Huntsman
Millard Wyatt

Office of..... Surveyor..... County of..... Union.....
 State of... Oregon....., I hereby certify that the within instrument was filed in this office
 for record on the... 4... day of... OCTOBER....., 1982
 Howard L. Perry..... by Gary L. Langlitz
 (COUNTY OFFICIAL) (DEPUTY)

T2S
 R35E R36E
 N 1/16
 S24 + S19
 1981
 OR PLS 1099



UNION COUNTY SURVEYOR

Date Received PO-798-276

Date Filed _____

By _____

File No. 279-84R