


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. 0-7

History of original corner establishment:

Not established during original survey.




Description of corner evidence found:

None.

Description of monument and accessories I established to perpetuate the original location of this corner:

Corner position established by survey and subdivision of Section 20.
At surveyed point set 2½"x30" galvanized pipe with brass cap stamped:
Set pipe 22" in ground with mound of stone and dirt to cap.



Bearing trees:

A P. Pine 17" dia. bears N20°E, 26.4 Ft. dist. scribed CN1/16 S20 BT.

A Douglas Fir 18" dia. bears N38°W, 13.4 Ft. dist. scribed CN1/16 S20 BT.

Set metal post 6 Ft. North of corner. Painted trees and attached signs per Standard Specifications For Cadastral Surveys, U.S.F.S. Region 6, Oct., 1979.

Corner falls on steep NE slope approx. 200 Ft. South of U.P.R.R. tracks and 550' South of Old Oregon Trail Hwy.

Compass Declination: 18½° East

I hereby certify the above described corner monument and/or accessories was established on August 3, 1982.

Witnesses: R. Orton
R. Scott



Office of.....Surveyor..... County of.....Union.....
State of.....Oregon....., I hereby certify that the within instrument was filed in this office
for record on the...4... day of...OCTOBER....., 1982.
.....Howard L. Perry..... by Gary L. Langlitz.....
(COUNTY OFFICIAL) (DEPUTY)

SURVEYOR

Date Received _____

Date Filed _____

By _____

282-84 R