


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:
Corner not previously established.



No record of subsequent monumentation found in Union County survey records.

Description of corner evidence found:
Corner not previously established.
See map of survey dated June, 1989.

UNION COUNTY SURVEYOR
Date Received 8-22-89
Date Filed 8-22-89
By G. LANGLITZ, DEPUTY
File No. 127-89 R

Description of monument and accessories I established to perpetuate the original location of this corner: At position determined by survey, I set a 2½" x 30" aluminum pipe with aluminum cap marked as shown, 28 inches in the ground, from which:


New BTs:
A 14 inch diameter Ponderosa Pine bears S44°E, 28.34 feet marked NW 1/16 S23 BT
A 17 inch diameter Ponderosa Pine bears N56°W, 4.48 feet marked X BT

Painted a 6 inch red band around all BTs and attached bearing tree and land survey monument signs.

Set a steel fencepost approximately 5 feet East with land survey monument and property boundary signs attached.

Raised a mound of stone around monument, 3 ft. base to top of cap.

I hereby certify that the above corner point was perpetuated as hereon described on June 4, 1989.



REGISTERED PROFESSIONAL LAND SURVEYOR

Handwritten signature of Duane I. Griffith
OREGON
JULY 10, 1964
DUANE I. GRIFFITH
644

I used a steel tape and magnetic compass in the establishment of new accessories. I used 17° East magnetic declination and the distances are to a 50d spike driven in the right side of the root crown. I attached a brass washer marked OPLS 644 to the BT blaze.

Office of..... County of.....
State of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19.....
..... by

(COUNTY OFFICIAL)

(DEPUTY)