


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. P-4

History of original corner establishment:

Not established during original survey.



Description of corner evidence found:

None

Description of monument and accessories I established to perpetuate the original location of this corner:

Corner location determined by surveying and subdivision of Section 19:

At surveyed point:

Set 2 1/2"x30" galvanized pipe with brass cap attached 24" in the ground stamped:

T2S R36E

E 1/16

C ——— | ——— C

S19

1981

ORPLS 1099

From which:

An 8" Douglas Fir bears S50°E 31.7 ft. scribed CE 1/16 S 19 BT.

A 12" Ponderosa Pine bears N61°E 41.2 ft. scribed CE 1/16 S 19 BT.


Attached 54-3 and 54-4 signs to BT's. Painted blazes and 6" red ring around BT's. Attached brass washers LS 099 to foot blazes. Set metal fence post 5 ft. north with 54-2 and 54-4. Set metal fence post 5 ft. west with 54-2 and 54-9 signs.

Corner falls on south slope 165 ft. West of South draw.

Compass Declination: 18 1/2° East

I hereby certify the above described corner monument and/or accessories was established as described on November 12, 1981.

Witnesses: Loren Huntsman
Millard Wyatt



Office of..... Surveyor..... County of..... Union.....
 State of..... Oregon..... I hereby certify that the within instrument was filed in this office
 for record on the 4 day of OCTOBER, 1982
 Howard L. Perry by *Gary L. Langlitz*
 (COUNTY OFFICIAL) (DEPUTY)

UNION COUNTY SURVEYOR

Date Received _____

☆ GPO—798-276

Date Filed _____

By _____

File No. 285-84 R