


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index No. P-7

History of original corner establishment:

Not previously established.



Description of corner evidence found:

None.

Description of monument and accessories established to perpetuate the original location of this corner:

Corner location determined by survey and subdivision of Section 20. At surveyed point set 2 1/2"x30" galvanized pipe with brass cap stamped:

Set pipe 24" in ground with mound of stone and dirt to cap.

Bearing Trees:

- A Douglas Fir 9" dia. bears S58°W, 38.2 ft., scribed C 1/4 S20 BT.
- A Pond. Pine 8" dia. bears N44°W, 54.4 ft., scribed C 1/4 S20 BT.

Attached brass washer stamped LS 1099 to foot blaze of BT's. Attached 54-3 and 54-4 signs to BT's and painted blazes and 6" band around BT's red. Attached 54-9 sign to metal post 5 ft. north of cor. Cor. falls on steep rocky S.E. slope 135 ft. south of top of ridge running S.E.


Compass Declination: 18 1/2° East

I hereby certify the above described corner monument and/or accessories was established as described on December 15, 1981.

Witnesses: Rodger Orton
Gary Langlitz

Office of..... Surveyor..... County of..... Union
State of..... Oregon.....

I hereby certify that the within instrument was filed in this office for record on the 4 day of OCTOBER, 1982
Howard L. Perry by Gary L. Langlitz
(COUNTY OFFICIAL) (DEPUTY)



UNION COUNTY SURVEYOR
Date Received _____
Date Filed <small>GPO 799-509</small> _____
By _____
File No. <u>286-84 R</u>