


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. P-10

History of original corner establishment:

Not previously established



Description of corner evidence found:

None

Description of monument and accessories established to perpetuate the original location of this corner:

Corner location determined by survey and subdivision of Section 21.

At surveyed point set 2 1/2" x 30" galvanized pipe with brass cap attached 8" in the ground stamped:

T2S R36E

W 1/16

C ——— C

S21

1981

OR PLS 1099

Built mound of stone and dirt to cap

From which:

A 16" Doug. Fir bears N24°E 91.2 ft. scribed CW 1/16 S21 BT

An 18" Pond. Pine bears N30W 130.7 ft. scribed CW 1/16 S21 BT

Attached 54-3 and 54-4 signs to BT's. Painted blazes and 6" red ring around BT's. Attached brass washers LS 1099 to foot blazes. Set metal post 5' north of corner with 54-4 and 54-9 signs.

Corner falls on east slope of north edge of large clearing 22' south of power line and 97' north of dirt road.

Compass Declination: 18 1/2° East

I hereby certify the above described corner monument and/or accessories was established as described on November 20, 1981.

Witnesses: Loren Huntsman  
Millard Wyatt

**REGISTERED  
PROFESSIONAL  
LAND SURVEYOR**

*Gary L. Langlitz*  
**OREGON**  
JULY 22, 1977  
**GARY L. LANGLITZ**  
1099

Office of..... Surveyor..... County of..... Union.....  
Oregon

State of..... I hereby certify that the within instrument was filed in this office

for record on the 4 day of OCTOBER, 1982.

Howard L. Perry by *Gary L. Langlitz*

(COUNTY OFFICIAL)

(DEPUTY)

**UNION COUNTY  
SURVEYOR**

Date Received \_\_\_\_\_  
★ GPO—758:276

Date Filed \_\_\_\_\_

By \_\_\_\_\_

File No. 288-84 R